

ROCK RASCAL Dop Pot - Model "D" Electric



FOR LAPIDARY USES

FILL COPPER PAN 3/4 FULL OF DOP WAX.
PLUG CORD INTO 115V AC OUTLET - DO NOT OPERATE DRY.
WAX WILL MELT TO PROPER CONSISTENCY IN 10-30 MINUTES.
CONSISTENCY MAINTAINED AS LONG AS UNIT IS PLUGGED IN.
WILL NOT OVERHEAT. NO VARIATION IN TEMPERATURE.
USES ONLY 50 WATTS.
ELIMINATES USE OF ALCOHOL LAMPS, CANS, ELECTRIC OR GAS PLATES.
NO MESS - CLEAN.
DISCONNECT UNIT WHEN JOB IS FINISHED.
PREHEAT STONES ON FLAT TOP.
DOP STICK RECEPTACLES ON SIDES.

FOR SILVER SMITHING USES

FILL COPPER PAN 3/4 FULL WITH WARM WATER.
ADD 2 TSP. SPAREX NO. 2 DRY COMPOUND: STIR UNTIL DISSOLVED.
PLUG INTO 115C AC OUTLET.
SOLUTION WILL WARM TO PROPER TEMPERATURE IN 15-30 MINUTES.
UNIT WILL MAINTAIN THE PROPER TEMPERATURE.
NOTE: ADD SOLUTION WHEN NECESSARY TO MAINTAIN 3/4 LEVEL.
USES ONLY 50 WATTS.
UNIT CAN ALSO BE USED TO WARM WAXES FOR MAKING OR REPAIRING WAX PATTERNS.

FULL FACTORY WARRANTY - REPLACEMENT COPPER PANS & HEATERS AVAILABLE.

NOTE: TO OPERATE PROPERLY, THE COPPER PAN MUST REST FIRMLY ON HEATER. ROUGH HANDLING IN SHIPPING MAY LOOSEN PAN. BEFORE USING PRESS PAN DOWN WITH FINGERS TO MAKE SURE IT IS PROPERLY SEATED AGAINST HEATER. TO REMOVE PAN, POSITION SCREW DRIVER UNDER LIP & PRY UP SLOWLY. REPLACE PAN BY INSERTING IN HOLE & PRESS FIRMLY AGAINST HEATER WITH FINGERS.

Johnson Brothers Lapidary

1452 N. Batavia St. # A, Orange, CA 92867

Ph: 714-771-7007

Web: www.JBFC.com - Email: sales@JBFC.com